

401647



992 OLD EAGLE SCHOOL ROAD  
SUITE 916  
WAYNE, PENNSYLVANIA 19087  
(215) 687-9510

**ORIGINAL**  
**(Red)**

May 30, 1984  
C-585-5-4-72  
68-01-6699

Mr. Harold Byer  
U.S. Environmental Protection Agency  
Sixth and Walnut Streets  
Philadelphia, PA 19106

Subject: Sampling Plan  
TDD No. F3-8405-15  
Bishop Tube Company  
Frazer, PA

Dear Mr. Byer:

The site inspection of the Bishop Tube Company has been scheduled for Wednesday, June 6, 1984. Access was granted by Mr. Miers C. Johnson, who is a project Engineer for Bishop Tube Company. Presently we are waiting to hear from PA DER whether they would like to join us during the site inspection.

The Bishop Tube Company is a manufacturer and seller in special seamless tubing for industrial use. They use solvents and acids in their production process and in the past they have used an unlined pit and on site cess pool to dispose of waste generated by the plant. The major concerns at the site are its effects on surface water and ground water contamination.

The proposed sampling locations include:

- o VOAs of 4 monitoring wells on site.
- o VOAs of upstream and downstream samples.
- o VOAs of 2 closed impoundments.
- o VOAs of 4 domestic wells including at least 1 upgradient well.

Modifications of the sampling plan may be made on site.

Mr. Harold Byer  
U.S. Environmental Protection Agency  
May 30, 1984 - Page 2  
Sampling Plan  
Bishop Tube Company

ORIGINAL  
(Red)

The total number of samples expected to be taken are 12 VOAs. These will be tested for volatile organics.

Mr. (b) (4) has been appointed Team Leader and will be responsible for the sampling plan.

Please endorse below and return with your approval or amendments to this plan. If you have any questions, please feel free to contact either Tom Fromm or myself.

Respectfully,

(b) (4)

Manager, FIT III

CM/GG/tb

Approved by:

(b) (4)

Date:

6/4/84

Amendments:

Attached are 3 §103(C) Notifications for  
Bishop Tube facilities. I believe they  
only represent 2 facilities. Please  
clarify this with the Owner and  
identify this in your report. Thank you